



Ref : ADM/LMN/2025/95

: المرجع

Date: 08/10/2025

: التاريخ

LOCAL MARINE NOTICE IN ABU DHABI

النشرة البحرية المحلية لإمارة أبوظبي

To : All users of waterways, mariners and maritime operators in Abu Dhabi

إلى : جميع مستخدمي الممرات المائية والبحارة والمشغلين البحريين في أبوظبي

Location : Waterways from East of Bu Tinah Island to West of Mubbaraz Island, Abu Dhabi

الموقع : الممرات المائية الممتدة من شرق جزيرة بوطينة

وحتى غرب جزيرة مبرز، أبوظبي

Subject : Offshore ADNOC Seismic Operations

الموضوع : عمليات مسح أدنوك الزلزالي

With reference to the Local Marine Notice (LMN) Ref: ADM/LMN/2025/79, issued on 24/08/2025, please be informed that seismic operations will continue in the Waterways from East of Bu Tinah Island to West of Mubbaraz Island, till 24th November 2025, as indicated on the updated illustrative map attached.

These areas are designated as NO GO zones for specific types of vessels, such as tugboats towing barges or platforms, marine units carrying subsea equipment, and cable-laying vessels, due to the risk of entanglement with seismic equipment. If other types of vessels are operating in these areas and intend to transit, please contact Offshore Safeena on CH 16/74 for further coordination.

All waterways users and marine operators are required to take all necessary actions and instruct their Masters/Operators to be vigilant and stay well clear of the area of operations and adhere to following Instructions:

بالإشارة إلى النشرة البحرية المحلية التي تحمل الرقم المرجعي: ADM/LMN/2025/79، الصادرة في 2025/08/24، نحيطكم علمه بمواصلة إجراء عمليات مسح زلزالي في الممرات المائية الممتدة من شرق جزيرة بوطينة وحتى غرب جزيرة مبرز، حتى 24 نوفمبر 2025، كما هو موضح في الخريطة المحدثة المرفقة.

يحظر رسو زوارق قطر البوارج أو المنصات، والوحدات البحرية التي تحمل معدات تحت سطح البحر، وسفن مد الكابلات في هذه المناطق، وذلك لتفادي خطر إعاقة المعدات والوسائل المستخدمة في المسح الزلزالي. وفي حالة مزاولة أي نشاط أو عند الرغبة في عبور هذه المنطقة، يرجى التواصل مع "أوفشور سفينة" على قناة 16/74 لمزيد من التنسيق.

على جميع مستخدمي الممرات المائية والمشغلين البحريين اتخاذ ما يلزم وإصدار التعليمات المطلوبة لربابنة سفنهم ومشغليها بضرورة توخي الحذر والبقاء بعيداً عن منطقة العمليات والالتزام بالتعليمات التالية:

1. على جميع المعنيين العلم بأنه سيتم نشر معدات المسح الزلزالي في قاع البحر وكذلك على سطح الماء بالمنطقة المشار إليها.

2. تمنع عمليات الصيد والرسو والتوقف والغوص في هذه المنطقة منعاً تاماً.

3. يجب قراءة هذه النشرة المحلية بالتزامن مع التعاميم الصادرة من شركة أدنوك بخصوص نفس المشروع.

4. مرفق أيضاً قائمة بسفن المسح الزلزالي المعنية وقنوات التواصل معها.

1. All concerned parties to be aware that in the area indicated, the seismic equipment will be deployed on the seabed as well as on water surface.
2. Fishing, anchoring stoppage and diving operations in this area are strictly forbidden.
3. This LMN to be read in conjunction with ADNOC Circulars/Marine Notices issued for the same project.
4. List of the relevant Siesmic Survey Vessels and their communication channels is attached as well.

سيف المهيري

الرئيس التنفيذي - أبوظبي البحرية


Capt. Saif Al Mheiri

CEO - Abu Dhabi Maritime



الخريطة التوضيحية والإحداثيات

Illustrative Map & Coordinates





BGP Crew 8652 - Focal Point



S/N	Name	Position	Location	Mobile	Email	Comments
1	Liu Jinkai	PRO	Base Camp	0545825175	adnoc8652_pr@bgp.com.cn	
2	Liu Liu	Fleet Manager	Offshore Safeena	0508937918	adnoc8652_fleet@bgp.com.cn	Offshore Fleet Operations

Onsite Boat Focal Point

S/N	Name	Position	Location	Mobile	Email	Comments
1	Mr Jelih/Mr Waleed	Radio Operator	Safeena Radio Room	0509951092	logisticsoffshoresafeena@gmail.com	VHF CH17/74
2	Capt. Marlon Marilao	Captain	Offshore Safeena	0566164824	safeena@nmdc-group.com	VHF CH17/74
3	Capt. Yusuf Tampang	Captain	Ramhan	0566852624	tug.ramhan@nmdc-group.com	VHF CH17/74
4	Capt. Oleksandr	Captain	DFKT2	+971 502447611 VSAT: +441246808032	bridge.dfkt2@bgp.com.cn	VHF CH17/74
5	Capt. Dede Sunandar	Captain	Stanford Volga	+971 507464621 VSAT: +1917 5085452	volga@stanford-marine.com	VHF CH17/74
6	Capt. Sukri Amri	Captain	Express99	0507957586 VSAT: +44 1346490795	express99@fleet.aesengroup.com	VHF CH17/74
7	Capt. Shang Hongkui	Captain	Hai Bao 2	0568758681 VSAT: +44 3300271180	haibao2@bgp.com.cn	VHF CH17/74
8	Capt. Sergii Koshterek	Captain	Hai Bao Qi	0502507918 Satellite: +44 2037694198	haibao7@bgp.com.cn	VHF CH17/74
9	Capt. Zamig Ismayilov	Captain	ADNOC A12	0507057469 VSAT: +88 2165 5000 995	adnoca12.master@zmfleet.com	VHF CH17/74
10	Capt. Rahmad Hidayat	Captain	ADNOC C08	0565339253	adnocc08@zmfleet.com	VHF CH17/74

S/N	Name	Position	Location	Mobile	Email	Comments
1	Liu Jinkai	PRO	Base Camp	0545825175	adnoc8652_pr@bgp.com.cn	
2	Sun Gengwu	SWC Manager	Offshore Safeena	0506473918	adnoc8652_sw@bgp.com.cn	Offshore SWC Operations

Onsite Boat Focal Point

S/N	Name	Position	Location	Mobile	Email	Comments
1	Tashkil Bashir Sangare	Skipper	HYWT 203	0566247691	adnoc8652_sw@bgp.com.cn	VHF CH74
2	Syed Maidul Islam	Skipper	HYWT 204	0542028537	adnoc8652_sw@bgp.com.cn	VHF CH74
3	Mohammad Moksudur Rahaman Sekh	Skipper	JHH 201	0547342624	adnoc8652_sw@bgp.com.cn	VHF CH74
4	Leonard Ismail	Skipper	LN 101	0565615940	adnoc8652_sw@bgp.com.cn	VHF CH74
5	Ridwansyah	Skipper	LN 102	0509161713	adnoc8652_sw@bgp.com.cn	VHF CH74
6	Rafiqul Mandal	Skipper	HYWT 302	0566910949	adnoc8652_sw@bgp.com.cn	VHF CH74
7	Alauddin sekh	Skipper	HYWT 304	0528445836	adnoc8652_sw@bgp.com.cn	VHF CH74
8	Randeep Kalyan	Skipper	HYWT 306	0544089335	adnoc8652_sw@bgp.com.cn	VHF CH74
9	Mohsin Daud Sangare	Skipper	HYWT 307	0507353842	adnoc8652_sw@bgp.com.cn	VHF CH74
10	Sriramamurthy Mylapilli	Skipper	HYWT 308	0501841913	adnoc8652_sw@bgp.com.cn	VHF CH74
11	Rauf Ameer Guhagarkar	Skipper	HYWT 109	0565593067	adnoc8652_sw@bgp.com.cn	VHF CH74
12	Anis Ahmad Majgaonkar	Skipper	HYWT 111	0506586380	adnoc8652_sw@bgp.com.cn	VHF CH74
13	Mansur Abd Rasyid Bujang	Skipper	HYWT 115	0563842926	adnoc8652_sw@bgp.com.cn	VHF CH74
14	Srinu Vadamodula	Skipper	HYWT 122	0503316918	adnoc8652_sw@bgp.com.cn	VHF CH74
15	Taksim Khan	Skipper	HYWT 137	0564852972	adnoc8652_sw@bgp.com.cn	VHF CH74
16	Hasanuj Jaman Sekh Najimuddin	Skipper	HYWT 138	0502932427	adnoc8652_sw@bgp.com.cn	VHF CH74
17	Jagadish Surakala Muthiraju	Skipper	HYWT 139	0501281300	adnoc8652_sw@bgp.com.cn	VHF CH74
18	Brajen Biswas	Skipper	RIGEL 5	0542283210	adnoc8652_sw@bgp.com.cn	VHF CH74
19	Jayantha Gundu Karkera	Skipper	RIGEL 6	0544708652	adnoc8652_sw@bgp.com.cn	VHF CH74
20	Shiv Chandra Mahto	Skipper	HZ 19	0505853126	adnoc8652_sw@bgp.com.cn	VHF CH74



Ref : ADM/LMN/2025/79 : المرجع
Date: 24/08/2025 : التاريخ

LOCAL MARINE NOTICE IN ABU DHABI

النشرة البحرية المحلية لإمارة أبوظبي

To : All users of waterways, mariners and maritime operators in Abu Dhabi

إلى : جميع مستخدمي الممرات المائية والبحارة
والمشغلين البحريين في أبوظبي

Location : Waterways from East of Bu Tinah Island to West of Mubbaraz Island, Abu Dhabi

الموقع : الممرات المائية الممتدة من شرق جزيرة بوطينة
وحق غرب جزيرة مبرز، أبوظبي

Subject : Offshore ADNOC Seismic Operations

الموضوع : عمليات مسح أدنوك الزلزالي

Please be informed that seismic operations will be conducted in the Waterways from East of Bu Tinah Island to West of Mubbaraz Island, from 25th August 2025 till 8th November 2025, as indicated on the illustrated map attached.

نحيطكم علماً بأنه سيتم إجراء عمليات مسح زلزالي في الممرات المائية الممتدة من شرق جزيرة بوطينة وحق غرب جزيرة مبرز، وذلك اعتباراً من 25 أغسطس 2025 وحتى 8 نوفمبر 2025، كما هو موضح في الخريطة المرفقة.

These areas are NO ANCHOR zones due to risk of entanglement in Seismic equipment. If you are operating in the area and need to anchor ,please contact Offshore Safeena on CH 16/74 for further coordination.

يُحظر الرسو في هذه المناطق، لتفادي خطر إعاقة المعدات والوسائل المستخدمة في المسح الزلزالي. وفي حالة مزاولة أي نشاط في المنطقة، وعند الحاجة إلى الرسو، يرجى التواصل مع "أوفشور سفينة" على قناة 16/74 لمزيد من التنسيق.

All waterways users and marine operators are required to take all necessary actions and instruct their Masters/Operators to be vigilant and stay well clear of the area of operations and adhere to following Instructions:

على جميع مستخدمي الممرات المائية والمشغلين البحريين اتخاذ ما يلزم وإصدار التعليمات المطلوبة لربانة سفنهم ومشغلها بضرورة توخي الحذر والبقاء بعيداً عن منطقة العمليات والالتزام بالتعليمات التالية:

1. All concerned parties to be aware that in the area indicated, the seismic equipment will be deployed on the seabed as well as on water surface.
2. Fishing, anchoring stoppage and diving operations in this area are strictly forbidden.
3. This LMN to be read in conjunction with ADNOC Circulars/Marine Notices issued for the same project.
4. List of the relevant Siesmic Survey Vessels and their communication channels is attached as well.

1. على جميع المعنيين العلم بأنه سيتم نشر معدات المسح الزلزالي في قاع البحر وكذلك على سطح الماء بالمنطقة المشار إليها.
2. تمنع عمليات الصيد والرسو والتوقف والغوص في هذه المنطقة منعاً تاماً.
3. يجب قراءة هذه النشرة المحلية بالتزامن مع التعاميم الصادرة من شركة أدنوك بخصوص نفس المشروع.
4. مرفق أيضاً قائمة بسفن المسح الزلزالي المعنية وقنوات التواصل معها.

سيف المهيري

الرئيس التنفيذي - أبوظبي البحرية

Capt. Saif Al Mheiri

CEO - Abu Dhabi Maritime

Abu Dhabi Maritime
PO Box 54477
Abu Dhabi, UAE


Telephone: +9712 695 2000
Facsimile: +9712 695 2177
Email: info@admaritime.ae

أبوظبي البحرية
ص.ب. 54477
أبوظبي، الإمارات العربية المتحدة





الخريطة التوضيحية والإحداثيات
Illustrative Map & Coordinates





BGP Crew 8652 - Focal Point



S/N	Name	Position	Location	Mobile	Email	Comments
1	Liu Hao	Operation APC/PRO	Offshore Safeena	0509780918	adnoc8652_pr@bgp.com.cn	
2	James Lacey	Fleet Manager	Offshore Safeena	0505071429	adnoc8652_fleet@bgp.com.cn	Offshore Fleet Operations
Onsite Boat Focal Point						
S/N	Name	Position	Location	Mobile	Email	Comments
1	Capt.Katan Syahrir	Captain	Offshore Safeena	0566164824	safeena@nmdc-group.com	VHF CH17/74
2	Capt.Sahidin Syamsuddin	Captain	Ramhan	0566852624	tug.ramhan@nmdc-group.com	VHF CH17/74
3	Capt. Nabil Moustafa	Captain	DFKT2	+971 502447611 VSAT: +441246808032	bridge.dftk2@bgp.com.cn	VHF CH17/74
4	Capt.Nurhanuddin Syamsuddin	Captain	Stanford Volga	0561761216 VSAT: +1917 5085452	volga@stanford-marine.com	VHF CH17/74
5	Capt.Yoni M. Maitulung	Captain	Express99	0507957586 VSAT: +44 1346490795	express99@fleet.aesengroup.com	VHF CH17/74
6	Capt. Shang Hongkui	Captain	Hai Bao 2	0568758681 VSAT: +44 3300271180	haibao2@bgp.com.cn	VHF CH17/74
7	Capt. Nizami Aghayev	Captain	Hai Bao Qi	0502507918 Satellite: +44 2037694198	haibao7@bgp.com.cn	VHF CH17/74
8	Capt.Ashraf Ahmed Raouf	Captain	ADNOC A12	0507057469 VSAT: +88 2165 5000 995	adnoca12.master@zmfleet.com	VHF CH17/74
9	Capt.Rahmad Hidayat	Captain	ADNOC C08	0565339253	adnocc08@zmfleet.com	VHF CH17/74

BGP Crew 8652 - Focal Point



S/N	Name	Position	Location	Mobile	Email	Comments
1	Liu Hao	Operation APC/PRO	Offshore Safeena	0509780918	adnoc8652_pr@bgp.com.cn	
2	Sun Gengwu	SWC Manager	Offshore Safeena	0506473918	adnoc8652_sw@bgp.com.cn	Offshore SWC Operations
Onsite Boat Focal Point						
S/N	Name	Position	Location	Mobile	Email	Comments
1	Tashkil Bashir Sangare	Skipper	HYWT 203	0566247691	adnoc8652_sw@bgp.com.cn	VHF CH74
2	Faisal Mustafa Mujaawar	Skipper	HYWT 204	0542028537	adnoc8652_sw@bgp.com.cn	VHF CH74
3	Faizan Faizahmed Bamne	Skipper	JHH 201	0509707183	adnoc8652_sw@bgp.com.cn	VHF CH74
4	Leonard Ismail	Skipper	LN 101	0543219916	adnoc8652_sw@bgp.com.cn	VHF CH74
5	Surdani Bin Sopari	Skipper	LN 102	0509161713	adnoc8652_sw@bgp.com.cn	VHF CH74
6	Prahar Prakash Bhubu	Skipper	HYWT 302	0563055657	adnoc8652_sw@bgp.com.cn	VHF CH74
7	Rafiqul Mandal	Skipper	HYWT 304	0566910949	adnoc8652_sw@bgp.com.cn	VHF CH74
8	Rauf Ameer Guhagarkar	Skipper	HYWT 306	0544089335	adnoc8652_sw@bgp.com.cn	VHF CH74
9	Alauddin Sekh	Skipper	HYWT 307	0528445836	adnoc8652_sw@bgp.com.cn	VHF CH74
10	Nayyar Babamiya Sansare	Skipper	HYWT 308	0506836048	adnoc8652_sw@bgp.com.cn	VHF CH74
11	Rauf Ameer Guhagarkar	Skipper	HYWT 109	0565593067	adnoc8652_sw@bgp.com.cn	VHF CH74
12	Anis Ahmad Majgaonkar	Skipper	HYWT 111	0506586380	adnoc8652_sw@bgp.com.cn	VHF CH74
13	Mesbur Rahman Sk	Skipper	HYWT 115	0569508494	adnoc8652_sw@bgp.com.cn	VHF CH74
14	Srinu Vadamodula	Skipper	HYWT 122	0503316918	adnoc8652_sw@bgp.com.cn	VHF CH74
15	Siva Prasad Vadamadula Pydi Raju	Skipper	HYWT 137	0508224391	adnoc8652_sw@bgp.com.cn	VHF CH74
16	Hasanuj Jaman Sekh Najmuddin	Skipper	HYWT 138	0502932427	adnoc8652_sw@bgp.com.cn	VHF CH74
17	Jagadish Surakala Muthiraju	Skipper	HYWT 139	0501281300	adnoc8652_sw@bgp.com.cn	VHF CH74
18	Brajen Biswas	Skipper	RIGEL 5	0542283210	adnoc8652_sw@bgp.com.cn	VHF CH74
19	Jayantha Gundu Karkera	Skipper	RIGEL 6	0544708652	adnoc8652_sw@bgp.com.cn	VHF CH74

